

OPERATING EXPERIENCE SUMMARY



Inside This Issue

- *Electrical fire traced to an overloaded extension cord used to power an air conditioner 1*
- *Three 5-pound steel plates fell from the ceiling when roofers cut support bolts 3*
- *An index of all OE Summary articles published in 2003 5*



U.S. Department of Energy
Office of Environment, Safety and Health

OE Summary 2003-26

December 29, 2003

With the full implementation of the redesigned Occurrence Reporting and Processing System (ORPS) on December 1, 2003, the Occurrence Reporting Binning and Tracking Tool (ORBITT) database has been discontinued. The ORPS database includes HQ Keywords that are equivalent to ORBITT bins to assist users in sorting through events to perform specific searches.

The old ORBITT bins have been crosswalked to the new HQ Keywords to provide data continuity.

Users may direct questions to Bal Mahajan by e-mail at bal.mahajan@eh.doe.gov.

RECEIVE E-MAIL NOTIFICATION FOR NEW OE SUMMARY EDITIONS

The process for receiving e-mail notification when a new edition of the OE Summary is published is simple and fast. New subscribers can sign up at the following URL: <http://www.eh.doe.gov/paa/subscribe.html>. If you have any questions or problems signing up for the e-mail notification, please contact Richard Lasky at (301) 903-2916, or e-mail address Richard.Lasky@eh.doe.gov.

Visit Our Web Site

Please check our web site every two weeks for the latest OE Summary. The Summary is available, with word search capability, via the Internet at www.eh.doe.gov/paa. If you have difficulty accessing the Summary at this URL, please contact the ES&H Information Center, (800) 473-4375, for assistance. We would like to hear from you regarding how we can make our products better and more useful. Please forward any comments to Frank.Russo@eh.doe.gov.

The OE Summary can be used as a DOE-wide information source as described in Section 5.1.2, DOE-STD-7501-99, *The DOE Corporate Lessons Learned Program*. Readers are cautioned that review of the Summary should not be a substitute for a thorough review of the interim and final occurrence reports.

EVENTS

1. OVERLOADED EXTENSION CORDS CAN CAUSE ELECTRICAL FIRES

Consumer Product Safety Commission (CPSC) investigations have found that overloaded, worn, and damaged cords are major factors in fires and accidents both at home and in the workplace. A recent fire at a DOE facility occurred because an air conditioner plugged into an extension cord overloaded the capacity of the cord.

On November 11, 2003, an early morning fire at Stanford Linear Accelerator Center (SLAC) resulted in severe smoke damage to electronic equipment and destroyed an air conditioner. No one was in the building at the time, but a maintenance worker saw the fire and alerted the fire department. Responders found the wall-mounted air conditioner plugged into an extension cord instead of a single-outlet circuit, as required. Based on burn patterns and damage to the extension cord, the SLAC fire marshal determined the extension cord was overloaded and was the point of origin for the fire. (OAK--SU-SLAC-2003-0004)

The fire was limited to the air conditioner and the extension cord. Photographs of the scene show that the fire originated at the floor and moved up the wall to the air conditioner (see Figure 1-1). An inspection of the electrical connection and interior components of the air conditioner




Figure 1-1. Burn pattern indicating point of origin

indicated that the damage was from external heat (i.e., from the fire), not from the failure of any air conditioner components. Figure 1-2 shows the burned cords.

Light-duty, household extension cords should never be used with high-wattage appliances such as air conditioners. Special, heavy-duty cords should be used instead. It is also essential for an extension cord to have a ground connection if the tool or appliance being plugged into it has a ground plug, and a three-prong connector should never be plugged into a two-pronged cord.



Figure 1-2. Burned cords

The gauge (diameter) of an extension cord wire must be large enough to handle the power being transferred through it. The gauge is based on the American Wire Gauge (AWG) system in which the larger the wire, the smaller the AWG number. For example, a 16-gauge (16 AWG), light-duty extension cord is rated to carry 13 amperes (up to 1,560 watts). A 16-AWG cord could be used safely for a typical table lamp, but a power tool that draws more power, such as a circular saw, would require a heavy-duty, 12-AWG cord.

To determine the proper gauge cord to use for a tool or appliance, find the amperage or wattage, which is usually displayed on a metal plate located on the housing, then choose the cord with the correct rating for the wattage. (Extension cords are usually labeled or tagged with rating information.) It is better to use a cord with a

heavier gauge (i.e., lower AWG number) than a lower-rated cord when the wattage of the appliance is not known. The rule of thumb is to use an extension cord with the same or larger wire size as the cord being extended.

Extension cords should not be used in place of permanent wiring. They should be used only for temporary service and for short periods of time and not as a “quick-fix” instead of installing an

electrical outlet. Temporary extension cords that are forgotten or overlooked can easily become a fire hazard. Had the air conditioner at SLAC been plugged into an electrical outlet, rather than an extension cord, the fire would not have occurred.

In their “Extension Cords Fact Sheet,” the CPSC estimates that an extension cord fire occurs approximately every 6 minutes. Such fires are responsible for more than \$50 million in property damage each year. CPSC also estimates that about 3,300 residential fires originate with extension cords each year, killing 50 people and injuring about 270 others. The most frequent causes of these fires are short circuits and overloading, damage, and misuse of extension cords. The fact sheet and other pertinent information can be accessed at <http://www.cpsc.gov/CPSCPUB/PUBS/16.html>.

A far more tragic fire occurred on June 11, 2002, in Siler City, North Carolina. That fire also started with an overloaded extension cord connected to an air conditioner. The cord “melted right into the floor and ignited the couch above it,” according to the county fire marshal. Firefighters found the light-duty extension cord stretched across the living room from the kitchen, powering a window-unit air conditioner that had been running steadily for days in 90° temperatures. Six family members, including three children, died in the fire.

Not only was the cord overloaded in the Siler City fire, but the length of the extension cord contributed to an already hazardous condition. Based on its gauge, an extension cord can power an appliance of a certain wattage only at specific distances. As the cord gets longer, its current-carrying capacity is reduced. For example, a 16-AWG cord less than 50 feet long can power a 1,625-watt appliance, but if the cord is longer than 50 feet, it can power an appliance only up to 1,250 watts.

Damaged extension cords can also be dangerous. Touching even a single exposed strand of wire on a damaged cord can result in an electrical shock or burn. OE Summary 2003-20 reported on the safety hazards of miswired or damaged extension cords. The Office of Environment, Safety and Health reviewed 24 events across the complex that involved extension cords or power strips and found that 13 of these events resulted in electrical shocks.

EXTENSION CORD SAFETY

- Use extension cords only when necessary and only on a temporary basis.
- Use only special, heavy-duty extension cords for high-wattage appliances such as air conditioners, portable electric heaters, or freezers.
- Do not overload extension cords by plugging in equipment/appliances that draw more watts than the rating of the cord.
- Check the plug and the body of the extension cord while it is in use. If the cord feels hot or if there is a softening of the plastic, the plugs or connections may be failing, and the extension cord should be replaced.
- Never use an extension cord while it is coiled or looped, and never cover any part of the cord with newspaper, clothing, rugs, or other objects while it is in use.
- Never place an extension cord where it may be damaged by heavy furniture or foot traffic or use staples and nails to attach the cord to baseboards or another surface.
- Use only extension cords with labels indicating certification by an independent testing lab, such as UL (Underwriters Laboratories) or ETL (Electrical Testing Laboratories). These cords meet current industry safety standards.
- Never leave an extension cord plugged in when it is not in use. The cord will conduct electricity until it is unplugged from the outlet.
- Do not use extension cords that are cut or damaged.

An August 12, 2003, UL news release, "Extension Cords: Not 'One Size Fits All,'" contains more information about safely using extension cords. The news release is available at the UL website, <http://www.ul.com/consumers/cords.html>.

Extension cords should not be used in place of permanent wiring. When extensions cords are used, it is important to ensure that they are the correct type, gauge, and length to handle the power draw of the appliance/equipment being plugged into the cord.

KEYWORDS: *Extension cords, power cord, miswired, electrical fire*

ISM CORE FUNCTIONS: *Analyze the Hazards, Develop and Implement Hazard Controls, Perform Work within Controls*

2. STEEL PLATES ACCIDENTALLY FALL FROM CEILING WHEN ROOFERS CUT SUPPORT BOLTS

On August 28, 2003, at the Oak Ridge Y-12 Site, roofers cut several bolts protruding above the roofline of a building, allowing steel plates inside the building to fall to the floor. One of the 5-pound steel plates fell from the ceiling and landed about 15 feet away from a worker. The roofers assumed they were authorized to eliminate obstructions that interfered with a smooth roof surface. No injuries or damage to equipment resulted from this near-miss occurrence. (ORPS Report ORO--BWXT-Y12NUCLEAR-2003-0041; final report filed October 29, 2003)

Roofers were installing new insulation and a new roof membrane above a processing area in the building and needed to cut several protruding bolts. They believed the bolts only held angle irons in place on the roof, not the ceiling plates inside the building. Three steel plates (6 inches by 6 inches by ¼-inch), weighing about 5 pounds each, fell more than 10 feet to the floor. Two other plates were dislodged; one was on an I-beam and the other remained attached by a single intact bolt. Roofers had cut similar bolts in the past, but in those cases

the steel plates were supported by steel beams directly below the roof deck and were not dislodged. Investigators identified work planning, work authorization, and work execution deficiencies as causal factors for this event. They determined that the job hazard analysis for the task did not address the potential for falling objects that could affect operations areas inside the facility. In addition, work planners did not properly identify which penetrations were to be removed and did not specify that the area below the roof was to be cleared and roped off to protect personnel against falling objects.

GOOD PRACTICES FOR WORK MANAGEMENT

- Ensure that a comprehensive job hazards analysis is performed and documented.
- Ensure that controls for the hazards identified in the job hazards analysis are developed.
- Ensure that the work package includes the means to implement the hazard controls identified.
- Ensure that the work authorization process follows established processes and does not take shortcuts.
- Perform an independent assessment of the work planning and authorization processes before the work is started.
- Execute the work in accordance with established personnel safety requirements and practices.
- Provide direct and detailed oversight of subcontractors to ensure that they do not create hazards while performing their tasks.

Work authorization deficiencies included directing the roofers to cut the bolts without specifying that they needed to inspect the inside of the roof and consider the potential hazards. Work supervisors did not use established processes and procedures for authorizing removal of the bolts. Investigators also identified flaws in work execution, including the following.

1. The roofers did not notify shift operations personnel in the building before starting work.
2. The roofers did not stop work and evaluate the change in the scope of the work package when they encountered the bolts protruding above the roofline.

A similar incident in which roof repair workers compromised the safety of building inhabitants occurred at the Los Alamos National Laboratory on April 24, 2003. In this near-miss occurrence, a monorail crane I-beam support at roof level was discovered with all 12 of its support bolt heads ground off. The I-beam weighed approximately 1½ tons, and was located at ceiling level in an area occupied by workers on a daily basis. The I-beam did not fall because it was anchored at one end by four bolts in an 8-inch-thick reinforced concrete wall. This semi-detached condition of the crane rail, cantilevered from a concrete wall at one end, may have existed without detection for nearly 2 years. (ORPS Report ALO-LA-LANL-NUCSAFGRDS-2003-0001)

Facility managers had the crane removed after this occurrence because it had not been used for several years and its maintenance requirements outweighed its usefulness. Technical personnel revised the annual inspection checklists for cranes and hoists to specifically identify what components should be inspected (e.g., support plates, anchor bolts) and to require detailed scrutiny by inspectors.

Figure 2-1 shows the as-discovered condition of the I-beam crane rail that was unsupported from above. As shown in the figure, the free end of the beam (opposite the hoist location) is lower than the end attached to the wall. (The visible portions of the three detached support struts increase in size from left to right in the photo.) Figure 2-2 shows where one of the three I-beam support struts was attached to the roof structure above the drop ceiling. Each of the three struts was attached by four bolts, one in each corner of the strut plate. Figure 2-3 shows one of the 12 bolts after the bolt head had been ground off.




Figure 2-1. As-found condition of the I-beam crane rail

A Lessons Learned document was prepared for this event, (SELLS identifier 2003-LA-LANL-PS7-0004), entitled *Near Miss to a Serious Personal Injury: Monorail Crane I-Beam Support Found with Support Bolt Heads Cut*. This document is available from the SELLS website at <http://tis.eh.doe.gov/ll/listdb.html>.



Figure 2-2. *Strut and support plate, with four missing bolts*



Figure 2-3. *Support bolt after its head was ground off*

These events underscore the importance of following established procedures and practices in the planning, authorization, and execution of work tasks. Planning includes preparation of a comprehensive job hazards analysis, where potential hazards such as falling objects are identified and analyzed. The authorization step includes verification by senior managers that relevant processes and procedures have been addressed during work planning. Work execution includes ensuring that workers are sufficiently experienced and trained to perform the tasks safely and providing sufficient oversight of subcontractors to ensure that they do not create hazards (such as falling objects) as they perform their tasks.

KEYWORDS: *Falling objects hazard, roof refurbishment, near miss*

ISM CORE FUNCTIONS: *Define the Scope of Work, Analyze the Hazards, Develop and Implement Hazard Controls, Perform Work within Controls*

INDEX OF OE SUMMARY ARTICLES PUBLISHED IN 2003

OE SUMMARY 2003-25 (Published 12/15/03)

Title	OR Number
Incorrect Equipment Selection Results in Personnel Injury	ORO--BNFL-K31-2003-0002
Personnel Error Causes Significant Injury	RL--PHMC-GPP-2003-0004
Two Electrical Shock Events Occur at the Same Site within Three Days	ORO--BWXT-Y12CM-2003-0003
Waste Stack Topples onto Forklift	ORO--BWXT-Y12SITE-2003-0007
	ID--BBWI-RWMC-2003-0005



OE SUMMARY 2003-24 (Published 12/01/03)

Title	OR Number
Near Miss: Pipefitter Cuts into Energized Conductor	ALO-LA-LANL-ADOADMIN-2003-0002
Fire Ignites in Waste Drum Being Vented	ID--BNFL-AMWTF-2003-0008
Workers Cleaning Hot Cell Window Splashed with Acid	ORO--ORNL-X10NUCLEAR-2003-0020
Employee Injuries Cost U.S. Businesses Nearly \$1 Billion Per Week	N/A



OE SUMMARY 2003-23 (Published 11/17/03)

Title	OR Number
Near Miss: Breached Pressurized Fire Extinguisher Becomes a Projectile	ORO--BJC-PGDPENVRES-2003-0016
Management and Control of Shock-Sensitive Chemicals	ORO--ORNL-X10CENTRAL-2003-0006
Three Machine Shop Accidents Result in Two Worker Injuries and a Near Miss	CH-BH-BNL-NSLS-2003-0002
	CH-BH-BNL-BNL-2003-0012
	ORO--BWXT-Y12SITE-2003-0015
Annual Freeze Protection and Winterization Reminder	RFO--KHLL-ANALYTOPS-2003-0004
	RFO--KHLL-WSTMGTOPS-2003-0024



OE SUMMARY 2003-22 (Published 11/3/03)

Title	OR Number
Electrical Near Miss During Wall Penetration	NVOO--BN-NLV-2003-0003
Fire Suppression System Found in Degraded Condition	ALO-LA-LANL-ADOADMIN-2003-0004
Spray Lubricants Can Cause Fires in Paper Shredders	ALO-LA-LANL-MATSCCMPLX-2003-0002
Near Miss Emphasizes the Need to Inspect Ladders Before Using	SELLS Identifier 2003-SR-WSRC-0018



OE SUMMARY 2003-21 (Published 10/20/03)

Title	OR Number
Near Miss as Alligator Shear Actuates Unexpectedly	ORO--BWXT-Y12NUCLEAR-2003-0035
Worker Injured when File Cabinet Falls Over While Being Moved	SELLS Identifier 2003-SR-WSRC-0017
Worker Injured when Corroded Step Breaks	SR--WSRC-FDP-2003-0005
Failures to Implement Lesson Learned Result in Near Misses	RL--PHMC-200LWP-2003-0003



OE SUMMARY 2003-20 (Published 10/06/03)

Title	OR Number
Overloaded Trailer Causes Transportation Accident	ALO-AO-BWXP-PANTEX-2003-0038
Heavy Cable Trench Cover Dropped on Energized Power Cable	RP--CHG-TANKFARM-2003-0043
Unknown Safety Hazards—Miswired and Damaged Extension Cords	N/A
INEEL Shares Best Practices for Contamination Control	N/A
IDEAL Industries Recalls Voltage Testers	N/A



OE SUMMARY 2003-19 (Published 09/22/03)

Title	OR Number
Cabinet Anchor Bolt Penetrates Energized Cable	ID--BBWI-TRA-2003-0006
Safety Assessment Identifies Use of Numerous Deficient Scaffolds	ID--BBWI-WASTEMNGT-2003-0007
Aerosol Containers Inside Vehicles May Explode in Hot Weather	N/A
Small Gasoline-Powered Engines Can Present a Carbon Monoxide Hazard	N/A



OE SUMMARY 2003-18 (Published 09/08/03)


Title	OR Number
Technical Safety Requirements Violation—Combustibles Control	NVOO--BN-NTS-2003-0009
Review of Forklift Events Reported in 2003	N/A
Near Miss: Underground Electrical Cable Snagged and Cut	ALO--KO-SNL-6000-2003-0004
Hydrochloric Acid Causes Cylinder Rupture	NVOO--BN-NTS-20003-0011

**OE SUMMARY 2003-17** (Published 08/25/03)

Title	OR Number
Underrated Hoist Used to Operate Hot Cell Door	ORO--ORNL-X10NUCLEAR-2003-0003
Incorrectly Wired Circuits Result in an Electrical Shock	ORO--ORNL-X10SNS-2003-0002
Degraded Bungs on Waste Drums Allow Water Intrusion and Spread of Contamination	ORO--BJC-K25WASTMAN-2003-0006
Laboratory Technician Cuts into Pressurized UF ₆ Cylinder Found in Salvage Yard	Sells Identifier LL-2003-LLNL-19

**OE SUMMARY 2003-16** (Published 08/11/03)

Title	OR Number
Accumulation of Dust Causes Explosion at Manufacturing Plant	N/A
Worker Injured by Electrical Shock	ALO-LA-LANL-NUCSAFGRDS-2003-0002
Unplanned Equipment Modification Leads to Bridge Crane Damage	CH-AA-ANLW-AL-2003-0002
Worker Punctures Arm with Knife	RFO--KHLL-SOLIDWST-2003-0018

**OE SUMMARY 2003-15** (Published 07/28/03)

Title	OR Number
Zero-Energy Check Reveals Energized Switch	RL--PHMC-WRAP-2003-0002
Near Miss—Pressurized Air Hose Whips Violently	RFO--KHLL-771OPS-2003-0005
Pipe Left in Unsafe Condition Falls and Strikes Worker	OH-FN-FFI-FEMP-2003-0005
Dump Truck Damages Overhead Power Line	RP--CHG-TANKFARM-2003-0028

**OE SUMMARY 2003-14** (Published 07/14/03)

Title	OR Number
Technician Inadvertently Shuts Down Primary Ventilation System	RP--CHG-TANKFARM-2003-0011
Worker Cuts Energized Conductor Mistakenly Marked for Removal	ORO--BJC-X10ENVRES-2003-0002
Electrical Conduit Punctured by Steel Rod	RP--CHG-TANKFARM-2003-0032
Hazards of Nitrogen-Enriched Atmospheres	N/A

**OE SUMMARY 2003-13** (Published 06/30/03)

Title	OR Number
Electrical Safety Problems Continue in First Half of 2003	N/A
Near Miss—Worker on Elevated Platform Falls into Ladder Opening	CH-AA-ANLE-ANLEPFS-2003-0001
HEPA Filters Defaced with Graffiti	RFO--KHLL-771OPS-2003-0010
Fall from Steel Scaffolding During Disassembly	OH-MB-BWO-BWO04-2003-0008


**OE SUMMARY 2003-12** (Published 06/16/03)

Title	OR Number
Screw Penetrates Cable Causing Electrical Fault	Lessons Learned Identifier 2003-RL-HNF-0014
Unmonitored Crane Movements Create Hazards	ORO--SURA-TJNAF-2003-0001
Near Miss to Severe Injury when Tower Crane Rigging Strikes Worker	ALO-KO-SNL-5000-2003-0001
Near Miss—Piece of Connection Steel Falls from Roof	RP--BNRP-RPPWTP-2003-0005
	RL--BHI-DND-2003-0003



OE SUMMARY 2003-11 (Published 06/02/03)

Title	OR Number
Communication and Work Planning Problems Result in Potential Asbestos Exposures	ALO-KO-SNL-NMFAC-2003-0002
Two Workers Injured in Construction Accident	ALO-KO-SNL-NMFAC-2003-0005
Grounding Device Not Covered Under Lockout/Tagout	ID--BBWI-TRA-2003-0003
Combustible Materials Near Torch Cutting Catch Fire	SR--WSRC-FDP-2003-0008

**OE SUMMARY 2003-10** (Published 05/19/03)

Title	OR Number
Notice: Defective Collapsible Fuel Tanks Identified	N/A
Electrical Arc Indicates Inadequate Lockout/Tagout	ALO-AO-BWXP-PANTEX-2003-0008
Near Miss when Waste Container Drops from Hoist	RL--BHI-ERDF-2003-0002
Fabricated Spray Lance Ruptures when Overpressurized	SR--WSRC-HTANK-2003-0010
Researcher Receives Electrical Shock	RL--PNNL-PNNLBOPER-2003-0007
Electrical Circuit Breaker Locking Device Problems	ORO--BJC-K25GENLAN-2003-0007

**OE SUMMARY 2003-09** (Published 05/05/03)

Title	OR Number
Fires in Laboratory Fume Hoods	RL--PNNL-PNNLBOPER-2003-0004
	GO--NREL-NREL-2002-0001
Energized Power Line Damaged During Excavation	ORO--ORNL-X10SNS-2003-0001
Bolt Bag Contents Drop from Tower Crane Internal Hoist	RP--BNRP-RPPWTP-2003-0004
The Importance of Accurate Occurrence Reporting	ALO-LA-LANL-TA55-2001-0005

**OE SUMMARY 2003-08** (Published 04/21/03)

Title	OR Number
Near Miss: Powered Air-Purifying Respirator May Fail if Bumped	ID--BBWI-TAN-2003-0002
Mislabeled Circuit Breaker Creates Worker Safety Hazard	RL--BHI-ERDF-2003-0001
Catastrophic Failure of Hook Results in Near Miss	ID--BBWI-CFA-2003-0006
Electrical Near Miss Cleaning HVAC System	RP--BNRP-RPPWTP-2003-0002
Hydraulic Shear Failure Causes Worker Injury	SR--WSRC-FDP-2003-0001

**OE SUMMARY 2003-07** (Published 04/07/03)

Title	OR Number
Near Miss when Chemical Reaction Vessel Explodes	ALO-LA-LANL-CHEMLASER-2002-0001
Mixing Chemicals Can Create Storage Hazards	SELLS Identifier LL-2003-LLNL-06
Banned Respirator Hoods Purchased and Used	RL--PHMC-CENTPLAT-2003-0005
Unsafe Use of Hydraulic Power Unit Results in Near Miss to Severe Injury	ALO--VWID-WIPP-2003-0001
Near Miss: Energized Conductor Cut During Demolition	OH-MB-BWO-BWO04-2003-0002

**OE SUMMARY 2003-06** (Published 03/24/03)

Title	OR Number
Buried Conduit Partially Severed While Cutting Asphalt	OAK--LLNL-LLNL-2003-0001
Type B Investigation of Worker Injury in Fall from Ladder	OAK--SU-SLAC-2003-0001
Unsecured Scaffold Extension Results in Near Miss	RL--PHMC-324FAC-2003-0002
Lockout/Tagout Violations and Lessons Learned	N/A
Safety Alert Involving Transportation of Compressed Gas Cylinders	N/A

**OE SUMMARY 2003-05** (Published 03/10/03)

Title	OR Number
Workers Injured when Gas Drying Units Rupture	ID--BBWI-TOWN-2002-0006
Unsecured Nine-Ton Load Falls off Truck During Transport	ID--BBWI-CFA-2003-0001
Sharing Lessons Learned Helps Identify Suspect/Counterfeit Bolts in Tie-Down Straps	OH-WV-WVNS-HMT-2003-0001
Personal Protective Equipment Scorched by Sparks from Cutting Saw	ORO--BJC-K25-GENLAN-2003-0001
Inadequate Weld Examinations Result in Enforcement Conference	ORO--BWXT-Y12SITE-2002-0015



OE SUMMARY 2003-04 (Published 02/24/03)

Title

Carpenter Injured by Flying Table Saw Guard
Occupational Exposure Due to Inadequate Job Planning
Communication Cable Severed During Excavation
Worker Injured in Fall From Stacked Waste Containers
Intentional Violation of Work Controls

OR Number

SELLS Identifier LL-2002-LLNL-34
SR--WSRC-RBOF-2002-0004
CH-BH-BNL-PE-2003-0001
NVOO--BN-NTS-2003-0001
ID--BBWI-SMC-2003-0001



OE SUMMARY 2003-03 (Published 02/10/03)

Title

Tank Falls on Electrical and Steam Lines
Forklift Narrowly Misses Worker
Operator Errors Result in Bagless Can Weld Failures
Shock-Sensitive Chemicals Discovered in Waste Drums

OR Number

OH-FN-FFI-FEMP-2002-0041
RFO--KHLL-ENVOPS-2003-0001
SRS--WSRC-FBLINE-2003-0001
SR--WSRC-SLDHZD-2003-0002



OE SUMMARY 2003-02 (Published 01/27/03)

Title

Application of Risk-Based Decision Making—
Review of Locomotive Derailment Event
Inattention to Detail Results in Inadequate Respiratory
Protection
Near Miss: Truck Pulls Down Electrical Lines
Two Cranes Collide at Construction Site

OR Number

SR--WSRC-SUD-2002-0006
RFP--KHLL-NONPUOPS1-2002-0005;
RFO--KHLL-NONPUOPS1-2002-0009
ORO--BWXT-Y12CM-2002-0002
RP--BNRP-RPPWTP-2002-0012



OE SUMMARY 2003-01 (Published 01/13/03)

Title

Temporary Window Cover Falls to Floor
Near Miss—Worker Cuts Into Electrical Conduit
Water Spray Damages Energized Electrical Equipment
Near Miss As Steel Plate Slips from Lifting Fixture

OR Number

OAK--SU-SLAC-2002-0010
RFO--KHLL-374OPS-2002-0003
ALO-AO-BWXP-PANTEX-2002-0057
RFO--KHLL-D&DOPS-2002-0001

